

The Video in Motion interface for Volkswagen vehicles with ZAB navigation system.



General

With the Volkswagen ZAB navigation system in combination with OEM TV-tuner or DVD player it is not possible to watch TV or DVD on the navigation screen while driving. The Video in Motion Interface enabling built in DVD and TV picture to be viewed whilst on the move. This is ideal for passengers inside the car who wants to watch DVD or TV in motion.

Features

- #Plug and play
- #Easy connection
- #CAN-BUS Technology
- #NO interruption of the board electronics
- #Seat computer does not see the interface.

Delivery Package:

- TV free module
- Instructions with pictures
- Invoice
- One year warranty
- One year software warranty

Extra information

*Watching DVD or TV and navigate at the same time is NOT possible. The interface need to be deactivated.

*Activation/deactivation of the interface via an external switch or via the track+ button of the navigation system.

Legal information:

This interface should be used to display fixed menus during your journey, for example the MP3 menu for DVD upgrades. The driver of the vehicle must never be distracted by moving pictures. In most countries/states, watching movies whilst driving is prohibited. Therefore, we do not accept any liability for material damage or personal injury resulting, directly or indirectly, from the installation or the operation of this TV-free interface.

Tv vrijeschakeling / TV free / TV vrijeschakelen

Interface and software basic information:

New cars can be based on new hardware and software versions not compatible with previous ones. The period required by programmers to study these new solution is about 2/3 months. It's impossible to be sure about interfaces compatibility on cars released earlier than 3/4 months.

Car manufacturers release new software versions without advise which could compromise the compatibility with third party electronic devices. We try to optimize all the information as soon as possible.

We suggest to not update the car software if not strictly required.

The same problems could be experienced on special version cars and on vehicles developed for different markets like American market or European market.

In many cases, updating the interface software is the same as replacing the interface itself. This means that the car must be disassembled as at the first installation.

Multimedia and CAN-BUS interfaces are very sophisticated devices which have to be installed in advanced and complex electronic car environments. The installation must be performed by highly experienced personnel. Also is it possible that the car won't except the interface for some reasons. In this case we have to look for alternatives.



Compatible with the following models of Volkswagen with ZAB



Not compatible with:

- MFD2 / RNS2
- MFD3
- RNS810
- RNS5001
- RNS510 / MFD3